

1/37




Fig. 1




Fig. 2

3/37




Fig. 3

4/37




Fig. 4

5/37




Fig. 5

6/37




Fig. 6

7/37




Fig. 7

8/37




Fig. 8

9/37




Fig. 9

10/37




Fig. 10

11/37




Fig. 11

12/37




Fig. 12

13/37




Fig. 13

14/37




Fig. 14

15/37




Fig. 15

16/37




Fig. 16

17/37




Fig. 17




Fig. 18

18/37




Fig. 19

19/37




Fig. 20

20/37




Fig. 21

21/37




Fig. 22




Fig. 23

23/37




Fig. 24

24/37




Fig. 25

25/37




Fig. 26

26/37




Fig. 27

27/37

Table 1 (Example of Judgment of Cause of Ejection Failure)

	Reference Value P1	Reference Value N1	Reference Value N2
Normal Ejection	0	0	0
Drying	0	1	1
Adhesion of Paper Dust	0	1	0
Intrusion of Air Bubble	1	0	0

Fig. 28




Fig. 29

29/37




Fig. 30

30/37




Fig. 31

31/37




Fig. 32

32/37

Table 2 (Example until 1/2 Cycle)

	T s	T (1/2)
Normal Ejection	0 0 0	0 0 0
Drying	0 1 1	0 1 1
Adhesion of Paper Dust	0 1 0	0 1 0
Intrusion of Air Bubble	1 0 0	1 0 0

Fig. 33

33/37




Fig. 34

34/37




Fig. 35

35/37




Fig. 36

36/37




Fig. 37

37/37




Fig. 38